

**Photo # 1**

**Date:** 9/7/2011

Mid City Plating Co. Inc.

**ID #** IND 006 049 456

**Photographer:**  
Joe Kelly

**Description:** View of the chemical storage area in the central portion of the site, near the location of the former RCRA closure, facing northwest.



**Photo # 2**

**Date:** 9/7/2011

Mid City Plating Co. Inc.

**ID #** IND 006 049 456

**Photographer:**  
Joe Kelly

**Description:** View of the chemical storage area in the central portion of the site, near the location of the former RCRA closure, facing west.



**Photo # 3**

**Date:** 9/7/2011

Mid City Plating Co. Inc.

**ID #** IND 006 049 456

**Photographer:**  
Joe Kelly

**Description:** View of inactive plating line in the north-central portion of the site, facing east-northeast



**Photo # 4**

**Date:** 9/7/2011

Mid City Plating Co. Inc.

**ID #** IND 006 049 456

**Photographer:**  
Joe Kelly

**Description:** View chemical storage totes, and trenches west of plating lines in the north-central portion of the site, facing south.





**Photo # 5**

**Date:** 9/7/2011

Mid City Plating Co. Inc.

**ID #** IND 006 049 456

**Photographer:**

Joe Kelly

**Description:** View of hazardous waste dumpster in the northern portion of the site for plating sludge (facing southeast).



**Photo # 6**

**Date:** 9/7/2011

Mid City Plating Co. Inc.

**ID #** IND 006 049 456

**Photographer:**

Joe Kelly

**Description:** Southern property line with chemical storage for southwestern plating lines in the background (facing east).



**Photo # 7**

**Date:** 9/7/2011

Mid City Plating Co. Inc.

**ID #** IND 006 049 456

**Photographer:**  
Joe Kelly

**Description:** View of loading docks and grass covered area in the eastern portion of the site (facing south, with printing facility in the background).



**Photo # 8**

**Date:** 9/7/2011

Mid City Plating Co. Inc.

**ID #** IND 006 049 456

**Photographer:**  
Joe Kelly

**Description:** View of the northern property line, facing west.

